

The following briefly describes the changes incorporated in the associated update. Each subsequent update contains all of the changes incorporated in the previous revisions.

Revision	Dated	Description
058	January 03, 2013	Revised “Copy With Inspection Year” function. Various program maintenance.
	July 23, 2012	Resolved issue with using dual regulators with a shared relief valve. Various program maintenance.
	January 27, 2011	Various program maintenance.
057	December 23, 2010	Revised Import/Export functions to use the Microsoft Jet 4.0 database engine - allowing these functions to work properly on Windows 7. Resolved issue with “Invalid Device Factor” calculation error message when using API 520 devices.
		Various program maintenance.
056	November 9, 2010	Various program maintenance.
054	September 30, 2010	Various program maintenance.
052	August 16, 2010	Added Images tab to Station Data Report. Resolved issue with merge and append routines not saving results have completion.
		Various program maintenance.
051	July 2, 2010	Resolved issue with including image files when bundling a database.
046	February 17, 2010	Various program maintenance.
043	November 9, 2009	Resolved issue with handling shared relief valve stations.
042	October 30, 2009	Added a Repair Database routine to the Utilities menu list.
		Various program maintenance.
040	August 25, 2009	Enabled Restore Previous Database File menu item.



Revision	Dated	Description
		Revised inspection status reporting for past due stations. Revised mass update handling of “For Year” inspection item. Revised Copy With New Inspection Year routine to allow User selection of reset of inspection values.
038	June 26, 2009	Resolved issue with clearing calculated values on Pop Up Station data screen. Resolved issue with importing GasValve monitor stations. Revised to automatically use system default image viewer.
037	May 26, 2009	Resolved various issues with importing GasValve database files.
	May 15, 2009	Resolved issue with intermediate component list when using the Pop-Up data screen to assign components ahead of a relief valve. Resolved issue with downstream device list when changing run type using the Pop-Up data screen. Resolved issue displaying component list using the Station Report.

